






- Measurement: number of pulses, period, frequency, rotational speed, working time, position from an incremental encoder.
- Advanced functions for the configuration of pulse signals, e.g. for counting slowly changing pulses.
- Two-line LCD display with high contrast and built-in backlighting.
- Possibility of displaying the measured value and time simultaneously or an uncalculated quantity
 or unit (programmable unit of measured quantity).
- Meter programming from keyboard or through the RS-485 interface by means of the free eCon software.
- Two additional binary inputs for pulse counting or as control inputs.
- 4 alarm outputs with signalling on LED diodes, working in 7 different modes (option).
- Conversion of any measured value into an analog signal 0/4...20 mA or 0...10 V (option).
- Storage of minimal and maximal values for all measured quantities.
- Built-in power supply of object transducers 24V d.c.
- 32-point individual characteristic for the measured value.
- Mathematical functions for converting the measured value.


EXAMPLE OF APPLICATION




Measurement and reading of the signal from the flow meter and encoder. The measured values are available via the analog output and the digital interface.









DATA VISUALISATION



lub



, MP





Two-line display.
Simultaneous preview of the measured value (top line) and the input signal not scaled (bottom line).


Programmable measurement unit chosen from 56 variants available in the menu. Additionally, the ability to define your own display unit.



Preview of current time on the bottom line of the display. Real-time clock with automatic winter/ summer time change function.



INPUT SCALING



Conversion of the measured quantity based on 32-point individual characteristics. It allows for the mapping of signals non-linear characteristics.












Conversion of the measured quantity by means of mathematical functions: \sqrt{x} , x^2 , 1/x, $(1/x)^2$, $\sqrt{(1/x)}$

ALARM FUNCTIONS



1 or 4 relay outputs with the indication on the display as an active alarm number.

Each alarm can be configured to operate in one of 7 modes, including REG mode for alarm control through RS-485 Modbus.



 $t \ge$ time delay --> Alarm activeted For alarm operation both conditions (value and time delay) must be met


Programmable alarm signal holding.
Once the alarm event has ceased,
the alarm status marker flashes
on the display until it is reset
by the user.

Individually programmable parameters for alarm activation and deactivation delay; the function can be used to prevent "false" alarms.

www.lumel.com.pl



ADVANCED MEASUREMENT CONVERSION FUNCTION




The measured value can be converted in series and the result can be displayed. After each conversion step, the signal can be used for retransmission on the analogue output or as an alarm source.

In practical use, the meter can read the value from an object-oriented transmitter and display the actual value within a limited range, e.g. flow, volume etc. At the same time, the input signal not scaled can be retransmitted to the PLC.


This function can be useful in applications where the signal is dynamic. The display can show the values averaged over time (easier signal observation).

On the analogue output instead, you can retransmit the signal without additional delays this also applies to the alarm outputs.

WALKING WINDOW ALGORITHM



Programmed averaging time according to the walking window algorithm with a set averaging time. Only available for non-count values such as period, frequency and speed.



Ability to measure the average, minimum or maximum value when displaying the walking window.




TECHNICAL DATA								
INPUTS								
Input type	Indication range	Klasa, błąd pomiaru						
MAIN INPUT								
Pulse counter	-99999999999	±1 impuls						
Slow-changing pulses counter	-99999999999	±1 impuls						
Period	0.000053600 [s] ¹	0.0012						
Frequency	0.01720 000 Hz ¹	0.0012						
Rotation speed	0999999	0.0012						
Encoder	0999999	±1 impuls						
Pulse counter with frequency measurement	0999999 0.01720 000 Hz ¹	±1 impuls 0.01						
Working time counter, time counter	0999999	0.5 seconds a day						
Current time		0.5 seconds a day						
ADDITIONAL INPUT								
Pulse counter	-99999999999	±1 pulse						
Slow-changing pulses counter	-99999999999	±1 pulse						
Period	0.000053600 [s] ¹	0.001 ²						
Frequency	0.01720 000 Hz ¹	0.001 ²						
Rotation speed	099999	0,001 ²						
Working time counter, time counter	099999	0.5 seconds a day						
Current time		0.5 seconds a day						


¹ In the case of frequency and period measurements, the maximum measurement time (signal period duration) is determined by the SAVG setting, which also narrows the measuring range ² The measurement error is defined as a percentage of the displayed value, not less than the error resulting from the gating time of 30 ns, eg for the displayed value of 1000.00 Hz, the measurement error will be 0.01 Hz + 0.03 Hz.


OUTPUTS									
Output type	Properties				Remarks				
Relay output	 1 x N0 contacts, load-carrying capacity 5A / 250 V a.c.; 5A / 30V d.c. 3 relays with changeover contact, load-carrying capacity 6A / 250V a.c.; 6A / 30V d.c.; 0,15A / 250V d.c. 		£.;						
Analog output		grammable 0/420 mA, load grammable 010 V, load resi			Error of analog output: 0.1% of the set range Additional error from temperature changes: 50% of the class/10K				
OC output	OC type, pas	sive npn, 30 V d.c./30 mA			voltageless output				
Auxiliary supply	24 V d.c./ 30	mA							
DIGITAL INTERFACE									
		Transmission protocol	Mode	Baud rate					
RS-485		MODBUS RTU	8N2, 8E1, 801, 8N1	2.4, 4.8, 9.6	, 14.4, 19.2, 28.8, 38.4, 57.6, 115.2 kbit/s				
EXTERNAL FEATURES									
Readout field		1 row: 6-digits; digits height 2 row: 5-digits; digits height		high contra	st LCD with backlight and programmable measuring unit				
Weight		< 0.25 kg							
verall dimensions		96 x 48 x 93 mm		mounting hole 92 ^{+0.6} x 45 ^{+0.6} mm					
3 · · · · · · · · · · · · · · · · · · ·				from terminal side: IP 10					
RATED OPERATIN	G CONDIT	IONS							
Supply voltage		85253 V a.c. (40400 Hz), 90300 V d.c. 2040 V a.c. (4565 Hz) / 2060 V d.c.		power consumption < 6 VA					
Temperature		ambient: -25 <u>23</u> 55°C		storage: -30					
Relative humidity		2595%		without condensation					
Operating position		any							
External magnetic field	DADILIEV	0400 A/m							
SAFETY AND COM	LARITII A	REQUIREMENTS							
Electromagnetic compatibility		noise immunity		acc. to EN 61000-6-2					
Isolation between circuits	·			acc. to EN 61000-6-4					
Polution level									
Installation category	ory III								
mstanation tategory		for supply circuits : 300 V		acc. to EN 61010-1					
Maximal phase-to-earth v	oltage	for other circuits: 50 V	acc. to EN 61010-1						
Altitude a.s.l.		< 2000 m							



CONNECTION DIAGRAMS







Description of signals on connection strips

Example of connecting an incremental encoder with PNP outputs

ORDERING CODE

	N32O	Χ	χ	XXXXXXX	Х	Х
Supply:						
85253 V a.c., 90300 V d.c.		1				
2040 V a.c./ 2060 V d.c.		2				
Additional outputs:						
1 relay output, RS-485			1			
4 relay outputs, RS-485			2			
4 relay outputs, RS-485, 1 analog output			3			
Version:						
standard				0000000		
custom-made*				XXXXXXX		
Language:						
Polish/English					М	
Acceptance tests:						
without additional quality requirements						0
with an extra quality inspection certificate						1
with an extra calibration certifiate						2
acc. to customer's request						Χ

^{*} only after agreeing with the manufacturer

ORDERING EXAMPLE:

N32O 130000000M0 means N32O meter with supply 85... 253 V a.c.,90...300 V d.c., with 4 relay outputs, RS-485 interface and 1 analog output, in standard version, polish-english language version, without additional quality requirements.

N32O-19A_en



LUMEL S.A.

ul. Słubicka 4, 65-127 Zielona Góra, Poland tel.: +48 68 45 75 100, fax +48 68 45 75 508 www.lumel.com.pl

Technical support:

tel.: (+48 68) 45 75 143, 45 75 141, 45 75 144, 45 75 140 e-mail: export@lumel.com.pl **Export department:**

tel.: (+48 68) 45 75 130, 45 75 131, 45 75 132 e-mail: export@lumel.com.pl

Calibration & Attestation: e-mail: laboratorium@lumel.com.pl